

# POWER METER SERVO METER

2 in 1


## 1. Special Features:

- 1.1 To measure the current, voltage, power
- 1.2 Record the biggest current value : If current more than the set, will automatically alarm
- 1.3 Record the minimum current value : If current less than the set, also will automatically alarm
- 1.4 Record operation in current curve
- 1.5 Records provided the capacity of the power value


## 2. Performance parameter:

2.1 SERVO METER - CH1	< Input Voltage Range	max. 8. 4V
	Input Current Range	max. 10A
2.2 POWER METER - CH2	< Input Voltage Range	max. 60V
	Input Current Range	max. 100A
2.3 Display	1.5 " TFT	
2.4 Weight	28g	
2.5 Dimension	58x45x9 mm	
2.6 Port	UNI / DC	
2.7 Non-self-powered		


## 3. Configuration:




★ When constantly work by CH2 in a larger current circumstances, it may need to add a cooling device (shown below), or may cause the display does not work, even damage the display.



## **4.Operating instructions**




#### 4.1 To measure the current, voltage, power menu.




When the voltage less than the set value, current more than the set, will show a warning While the voltage or current will be highlighted.

## 4.2 Current graph menu



#### 4.3 Warning settings



## Warning message

when current/voltage value over  
the setting value meter warning!

## 【Notice】

**DO NOT** use it for more than 10 seconds when the current value is close to 100A.