

- The part number on page 3 in the instruction manual for the **optional wood motor mount box** is incorrect. The correct part number is **GPMA4382.**
- The LiPo batteries listed on page 3 are no longer available. Following is an updated list:

## **6S BATTERIES:**

FlightPower 6S 5000mAh 30C (FPWP3506)

FlightPower 6S 5000mAh 50C (FPWP5506)

FlightPower 6S 5500mAh 50C (FPWP5556)

FlightPower 6S 5500mAh 70C (FPWP7556)

## **3S BATTERIES\*:**

FlightPower 3S 5000mAh 30C (FPWP3503)

FlightPower 3S 5000mAh 50C (FPWP5503)

FlightPower 3S 5000mAh 70C (FPWP7503)

FlightPower 3S 5500mAh 50C (FPWP5553)

<sup>\*</sup>Note: If using 3S batteries, two batteries connected in series are required (using a series adapter listed in the instruction manual).